



# JOHN GUMM BUILDING PROJECT UPDATE

## Columbia County, OR

### APRIL UPDATE

We are excited to report there is a lot of installation happening at the John Gumm Building! We have started asbestos abatement in the window restoration process at John Gumm. We have continued with door and frame installation and have prepped the floors for flooring install. We have also started exterior work and rebuilt the canopy on the west side of the building. We have also started installing casework.

### WHAT'S NEXT

Next, we will continue with the glass replacement for the window restoration, install flooring on levels 1 and basement, and finish prepping for the elevator arrival.



*Level 1 Floor Overlay*



*West Balcony Exterior Framing*



*Level 2 Casework Installation*